

AD-A256 148



AD

TECHNICAL REPORT ARCCB-TR-92033

**FAILURE ANALYSES OF
M3A1 BASEPLATE FOR 81-MM MORTAR 252**

STEVE TAUSCHER



JULY 1992



**US ARMY ARMAMENT RESEARCH,
DEVELOPMENT AND ENGINEERING CENTER
CLOSE COMBAT ARMAMENTS CENTER
BENÉT LABORATORIES
WATERVLIET, N.Y. 12189-4050**



APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

92-27022



28
pgs

DISCLAIMER

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

The use of trade name(s) and/or manufacturer(s) does not constitute an official indorsement or approval.

DESTRUCTION NOTICE

For classified documents, follow the procedures in DoD 5200.22-M, Industrial Security Manual, Section II-19 or DoD 5200.1-R, Information Security Program Regulation, Chapter IX.

For unclassified, limited documents, destroy by any method that will prevent disclosure of contents or reconstruction of the document.

For unclassified, unlimited documents, destroy when the report is no longer needed. Do not return it to the originator.

REPORT DOCUMENTATION PAGE

Form Approved
OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

1. AGENCY USE ONLY (Leave blank)		2. REPORT DATE July 1992		3. REPORT TYPE AND DATES COVERED Final	
4. TITLE AND SUBTITLE FAILURE ANALYSES OF M3A1 BASEPLATE FOR 81-MM MORTAR 252				5. FUNDING NUMBERS AMCMS No. 6126.23.1BL0.0 PRON No. 1A83RZ4YNMSC	
6. AUTHOR(S) Steve Tauscher					
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army ARDEC Benet Laboratories, SMCAR-CCB-TL Watervliet, NY 12189-4050				8. PERFORMING ORGANIZATION REPORT NUMBER ARCCB-TR-92033	
9. SPONSORING / MONITORING AGENCY NAME(S) AND ADDRESS(ES) U.S. Army ARDEC Close Combat Armaments Center Picatinny Arsenal, NJ 07806-5000				10. SPONSORING / MONITORING AGENCY REPORT NUMBER	
11. SUPPLEMENTARY NOTES					
12a. DISTRIBUTION / AVAILABILITY STATEMENT Approved for public release; distribution unlimited.				12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 200 words) A metallurgical evaluation of a failed 81-mm M3A1 mortar baseplate was undertaken. The evaluation consisted of the following analyses: visual, dye penetrant, scanning electron microscopy/electron dispersive spectroscopy, chemical, metallographic, and mechanical property. The investigation concluded that there was no evidence of a defective material condition and that the probable mode of failure was a ductile, fast fracture under high load.					
14. SUBJECT TERMS Baseplate, Fracture, Microstructure, Mechanical Properties				15. NUMBER OF PAGES 23	
				16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT UNCLASSIFIED	18. SECURITY CLASSIFICATION OF THIS PAGE UNCLASSIFIED	19. SECURITY CLASSIFICATION OF ABSTRACT UNCLASSIFIED	20. LIMITATION OF ABSTRACT UL		

TABLE OF CONTENTS

	<u>Page</u>
INTRODUCTION	1
PROCEDURE	1
RESULTS	2
Visual Examination/Macrofractography	2
Scanning Electron Microscopy/Energy Dispersive Spectroscopy	3
Chemical Composition	3
Metallographic Examination	4
Mechanical Property Testing	5
CONCLUSIONS	6
REFERENCES	7

TABLES

I. SUMMARY OF HIGH PRESSURE ROUNDS JUST PRIOR TO FAILURE	8
II. CHEMICAL COMPOSITION OF 2014 ALUMINUM BASEPLATE	9
III. MECHANICAL PROPERTIES	10

LIST OF ILLUSTRATIONS

1. Arrows pointing out cracks and fracture surfaces on M3A1 baseplate	11
2. Closer view of same baseplate	11
3. View of fracture through spade from underside of baseplate	12
4. Fracture at fillet in triangularly-shaped hole in baseplate	12
5. Surfaces of fracture through the spades	13

6.	Flow lines of the fracture through the spade	13
7.	Fracture surface at the fillet	14
8.	Flow lines of the fracture at the fillet	14
9.	Microvoid formation and enlargement about angular particles	15
10.	EDS analysis of angular particles shown in Figure 9	15
11.	Microstructure in longitudinal plane, as-polished	16
12.	Microstructure in longitudinal plane, Keller's reagent	16
13.	Microstructure in longitudinal plane, Keller's reagent	17
14.	SEM backscatter image of polished metallographic specimen	17
15.	EDS analysis of microstructural constituents shown in Figure 14	18
16.	SEM backscatter image of polished metallographic specimen	18
17.	EDS analysis of white microstructural constituent shown in Figure 16	19
18.	EDS analysis of small gray microstructural constituent shown in Figure 16	19
19.	Etched transverse microstructure, Keller's reagent	20
20.	Schematic of mechanical property specimen section	21

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Special

DEPT. OF THE ARMY

INTRODUCTION

In May 1988, Advanced Engineering Branch of Benet Laboratories was requested by Product Assurance Engineering Division of Watervliet Arsenal to conduct a metallurgical evaluation of an M3A1 baseplate, SN EXP6, which had failed during firing. Figures 1 through 4 show the baseplate. This baseplate was used in an ammunition test at Combat Systems Test Activity, Aberdeen Proving Ground, MD, when the failure occurred. The Weapon Record Data, 2408-4 card, indicated a total of 1997 rounds had been fired. The last "ZYGL0" fluorescent inspection was conducted on 13 August 1987 at 860 rounds and did not reveal any cracks. According to the Product Assurance Engineering Division, the failure occurred at 19 rounds into a firing test involving high pressure rounds (see Table I).

A search through archive records revealed that this baseplate was purchased from Bergman Forge on Contract 83-C-0133 which was amended to include eight thicker prototype baseplate forgings modified from Dwg. 7309126. It is unknown whether they were brought to SPEC QQ-A-367H, "Federal Specification for Aluminum Alloy Forgings." According to Bergman Forge personnel, the baseplates were forged at 750°F using 9-inch diameter by 9-inch long round 2014 aluminum alloy extrusions. Certification record data appear in Tables II and III.

PROCEDURE

A metallurgical evaluation consisted of the following analyses:

1. Visual examination
2. Dye-penetrant inspection
3. Scanning electron microscopy/energy dispersive spectroscopy
4. Chemical composition
5. Metallographic examination

6. Mechanical property testing

- a. Tensile
- b. Charpy impact toughness
- c. Fracture toughness
- d. Hardness

RESULTS

Visual Examination/Macrofractography

A visual examination of the baseplate (Figures 1 through 4) and of the fracture surfaces was conducted to identify any material and/or forging defects as well as to characterize the type of failure, i.e., fatigue, ductile, brittle, etc. An examination was also conducted to determine the origin of failure, if possible. Three fracture surfaces were created during the failure; two on the spades (Figures 2 and 3), one-third of the way from the hub to the outer ring, and one between the fillets of two adjacent triangularly-shaped holes (Figures 2 and 4). These locations have been previously identified as the areas of highest stress (ref 1), and have been the locations of cracking initiation in previous baseplate failures (ref 2), as well as fatigue-tested baseplates (ref 3).

These fracture surfaces were exposed for further examination as shown in Figures 5 through 8. The appearance of chevron-type markings indicates that this fracture, through the spades (Figures 5 and 6), initiated at the bottom of the spade and proceeded in a fast, unstable manner to the hub area. Neither a material or forging defect, nor evidence of fatigue were found at the fracture origin. However, the bottom of the baseplate, and the spades in particular, had been severely damaged and indented (see Figure 3). The appearance and the size of shear lips on this fracture indicate a relatively ductile type of failure.

Examination of the fracture surface at the hole fillets revealed chevron-type markings again which indicated that the fracture had initiated on one side and proceeded in a fast unstable manner through the spade to the other fillet. Close examination of the fracture origin, as determined by the chevron-type markings, did not reveal a pre-existing material or forging defect. Also, under stereoscopic examination, there was no evidence of a pre-existing fatigue crack. The presence of shear lips on this fracture surface also suggests a relatively ductile failure. Finally, a dye-penetrant inspection of the entire baseplate did not reveal any other cracks.

Scanning Electron Microscopy/Energy Dispersive Spectroscopy

Scanning electron microscopy (SEM) was utilized for a micro-examination of the fracture origins for pre-existing defects and to characterize the fracture mode. All three fracture surfaces were examined. Again, there was no evidence of a material or processing defect. Further, there was no fractographic evidence of a corrosion-assisted cracking process or fatigue striations. Figure 9 is a fractograph that shows microvoid formation and void enlargement about angular particles. This is a characteristic of a ductile fracture mode under high load. Several particles in the fracture surface were analyzed using energy dispersive spectroscopy (EDS) and were found to contain aluminum, silicon, iron, and manganese (Figure 10). The particles were thus identified as $(\text{FeMn})_3\text{SiAl}_{12}$, which is a particulate common to 2014-T6 aluminum alloy.

Chemical Composition

A spectrochemical analysis of the chemical composition was conducted in accordance with paragraph 4.4.1 of Specification QQ-A-367H. The chemical composition as reported by the vendor and as analyzed by Benet appears in Table II.

The two analyses agree and show that the baseplate met the current required chemical composition and is typical of 2014-T6, a copper-alloyed, age hardenable aluminum grade.

Metallographic Examination

A metallographic examination of the microstructure was conducted to verify that the baseplate had undergone proper melting, forging, and heat treatment practice. The examination was also used to help analyze the SEM and mechanical property data. Figures 11 through 13 show the microstructure in a longitudinal plane of polish, adjacent to an uncracked fillet at the triangular holes. Figure 11 is an as-polished surface, showing several constituents aligned in the direction of material flow from forging. There is no evidence of shrinkage or gas porosity. Figures 12 and 13 show the microstructure of the same sample etched with Keller's reagent in order to examine for grain contrast, grain boundary lines, eutectic melting, overaging, and for identification of the constituents. The figures show a fine dispersion of CuAl_2 particles throughout a fine-grained aluminum matrix (typical of T6 aging) which contained three other constituents common to 2014 and which were present as much larger particles.

EDS was utilized to identify the composition of the particles shown in Figure 11. Figures 14 through 18 illustrate the elements found in particles on the polished and etched surface of a metallographic specimen. This analysis of elements, coupled with the gray levels revealed by Keller's reagent in optical microscopy, identified the larger particle constituents as CuAl_2 , $(\text{FeMn})_3\text{SiAl}_{12}$, and $\text{Cu}_2\text{Mg}_8\text{Si}_6\text{Al}_5$.

There was no evidence of rosette-shaped dendritic patterns indicative of eutectic melting, a condition which renders an aluminum forging defective by localized, solid solution melting under excessively high temperature forging

conditions. Figure 19 shows the microstructure in a transverse plane of polish at higher magnification. Fine CuAl_2 precipitates outline a fine-grained aluminum matrix. Also visible, again, are large CuAl_2 precipitates (white, bottom right), larger $(\text{FeMn})_3\text{SiAl}_{12}$ particles (black, bottom and bottom left), and smaller $\text{Cu}_2\text{Mg}_8\text{Si}_6\text{Al}_5$ particles (gray, bottom right). These constituents, their size and amount, are typical for this alloy and do not indicate a defective melting practice.

Mechanical Property Testing

Mechanical property testing was conducted to verify that the baseplate met the requirements of Specification QQ-A-367H and that low mechanical properties did not contribute to the failure. Hardness, tensile, Charpy impact toughness, and fracture toughness specimens were taken from the baseplate at the locations and orientations shown in Figure 20. The grain flow pattern, as revealed by metallography, was used to sample for tensile properties parallel and perpendicular to the grain flow as specified in paragraph 4.2.3.1 of QQ-A-367H. Tensile, Charpy impact, and fracture toughness tests were conducted according to ASTM Methods E-8, E-23, and E-399, respectively. The properties are summarized in Table III and are representative of the fine-grained microstructures revealed through metallography. In all cases, the properties exceeded specified properties. Fracture toughness in this baseplate, which is not specified, was typical of that in 2014-T6 aluminum (ref 4). In summary, the mechanical properties in this baseplate are indicative of 2014-T6 alloy that has been properly melted and processed.

CONCLUSIONS

Baseplate SN EXP6 met all specifications in QQ-A-367H "Federal Specification for Aluminum Alloy Forgings," cited on Dwg. 11579870, M3A1 baseplate forging. There was no evidence of a defective material condition arising from either melting, forging, or heat treatment. Furthermore, there was no evidence of any pre-existing cracks in the plate. Fractography indicates that the primary mode of failure was a ductile, fast fracture under high load, at the highest stressed locations, with no detectable stable crack growth (fatigue) preceding the final failure.

REFERENCES

1. O'Hara, G.P., "Stress Analysis of a Mortar Baseplate as the Basis for Fatigue Testing," Technical Report ARLCB-TR-80017, Benet Weapons Laboratory, Watervliet, NY, May 1980.
2. Senick, J.R., "Failure Analysis of 81-mm Mortar Baseplate," Memorandum for Record, Advanced Engineering Section, Benet Weapons Laboratory, Watervliet, NY, November 1983.
3. Racicot, R.L., "81-mm Mortar Baseplate Dynamic Test," Memorandum Communication, Applied Mathematics and Mechanics Section, Benet Weapons Laboratory, Watervliet, NY, April 1980.
4. Aerospace Structural Metals Handbook, Metals and Ceramics Information Center, Battelle Columbus Laboratories, Columbus, OH, 1987 Edition.

TABLE I. SUMMARY OF HIGH PRESSURE ROUNDS JUST PRIOR TO FAILURE

Date	Round #	Cumulative	Pressure Reading (Ksi)	
			Gage Copper	Piezo
3/18/88	1	1979	14.9	15.2
	2	1980	15.2	15.0
	3	1981	15.3	14.9
	4	1982	15.5	15.2
	5	1983	15.8	15.7
	6	1984	15.4	15.1
	7	1985	16.0	15.0
	8	1986	14.7	15.1
3/22/88	9	1987	15.6	15.0
	10	1988	14.1	14.0
	11	1989	15.4	15.4
	12	1990	15.0	15.3
	13	1991	16.0	15.6
	14	1992	14.8	14.7
	15	1993	15.0	15.3
	16	1994	15.2	15.6
	17	1995	15.2	15.0
	18	1996	14.7	15.0
	19	1997	15.4	15.9

TABLE II. CHEMICAL COMPOSITION OF 2014 ALUMINUM BASEPLATE

	Required*	Vendor	Benet
Copper	3.9-5.0	4.2	4.2
Silicon	0.50-1.2	0.75	0.71
Iron	0.7 max	0.45	0.38
Manganese	0.40-1.2	0.63	0.63
Magnesium	0.20-0.8	0.52	0.40
Zinc	0.25 max	0.10	0.14
Titanium	0.15 max	0.04	0.03
Chromium	0.10 max	0.02	0.01
Nickel	-	-	-
Aluminum	Bal		
Other**	0.15 max total	-	<0.4

*Table I, 2014, p. 3, QQ-A-367H, "Federal Specification for Aluminum Alloy Forgings"

**An analysis for the following typical impurities in 2014 was made:
sodium, calcium, nickel, vanadium, sulfur, zirconium

TABLE III. MECHANICAL PROPERTIES

Specimen ID/ Orientation	0.2% Yield Strength (Ksi)	Ultimate Tensile Strength (Ksi)	% Elongation	70°F CVN (ft-lbs)	70°F K _{IC} Ksi√in.	Hardness	
						R _b	BHN
Required (Long) (Trans)	56 min 55 min	65 min 64 min	6% min 3% min	-	-	-	125 min
T ₁ (Long)	63.1	69.8	7.0			81	156
T ₂ (Long)	63.9	69.5	7.2				
T ₃ (Trans)	61.1	67.5	5.3				
T ₄ (Trans)	61.1	66.3	5.8				
F ₁ (Long)					-		
F ₂ (Long)					26.5		
F ₃ (Long)					23.2		
F ₄ (Long)					24.2		
C ₁ (Trans)				1.5			
C ₂ (Trans)				1.5			
C ₃ (Long)				2.5			
C ₄ (Long)				2.5			
C ₅ (Trans)				2.5			
C ₆ (Trans)				2.5			
C ₇ (Trans)				2.5			
C ₈ (Trans)				3.5			
C ₉ (Long)				2.5			
C ₁₀ (Long)				2.5			
C ₁₁ (Long)				3			
C ₁₂ (Long)				3			




Figure 1. Arrows pointing out cracks and fracture surfaces on M3A1 baseplate.




Figure 2. Closer view of same baseplate.



Figure 3. View of fracture through spade from underside of baseplate.



Figure 4. Fracture at fillet in triangularly-shaped hole in baseplate.




Figure 5. Surfaces of fracture through the spades.




Figure 6. Flow lines of the fracture through the spade.



Figure 7. Fracture surface at the fillet.




Figure 8. Flow lines of the fracture at the fillet.




Figure 9. Microvoid formation and enlargement about angular particles. (500X)




Figure 10. EDS analysis of angular particles shown in Figure 9.




Figure 11. Microstructure in longitudinal plane, as-polished.
(100X)




Figure 12. Microstructure in longitudinal plane, Keller's reagent.
(100X)



Figure 13. Microstructure in longitudinal plane, Keller's reagent.
(500X)



Figure 14. SEM backscatter image of polished metallographic specimen.
(1000X)




Figure 15. EDS analysis of microstructural constituents shown in Figure 14.



Figure 16. SEM backscatter image of polished metallographic specimen. (2500X)




Figure 17. EDS analysis of white microstructural constituent shown in Figure 16.





Figure 18. EDS analysis of small gray microstructural constituent shown in Figure 16.



Figure 19. Etched transverse microstructure, Keller's reagent.
(1000 \times)



Key: T - Tensile
 C - Charpy V-Notch
 F - Fracture Toughness

Figure 20. Schematic of mechanical property specimen section.

TECHNICAL REPORT INTERNAL DISTRIBUTION LIST

	NO. OF COPIES
CHIEF, DEVELOPMENT ENGINEERING DIVISION	
ATTN: SMCAR-CCB-DA	1
-DC	1
-DI	1
-DR	1
-DS (SYSTEMS)	1
CHIEF, ENGINEERING SUPPORT DIVISION	
ATTN: SMCAR-CCB-S	1
-SD	1
-SE	1
CHIEF, RESEARCH DIVISION	
ATTN: SMCAR-CCB-R	2
-RA	1
-RE	1
-RM	1
-RP	1
-RT	1
TECHNICAL LIBRARY	5
ATTN: SMCAR-CCB-TL	
TECHNICAL PUBLICATIONS & EDITING SECTION	3
ATTN: SMCAR-CCB-TL	
OPERATIONS DIRECTORATE	1
ATTN: SMCWV-ODP-P	
DIRECTOR, PROCUREMENT DIRECTORATE	1
ATTN: SMCWV-PP	
DIRECTOR, PRODUCT ASSURANCE DIRECTORATE	1
ATTN: SMCWV-QA	

• NOTE: PLEASE NOTIFY DIRECTOR, BENET LABORATORIES, ATTN: SMCAR-CCB-TL, OF ANY ADDRESS CHANGES.

TECHNICAL REPORT EXTERNAL DISTRIBUTION LIST

	<u>NO. OF COPIES</u>		<u>NO. OF COPIES</u>
ASST SEC OF THE ARMY RESEARCH AND DEVELOPMENT ATTN: DEPT FOR SCI AND TECH THE PENTAGON WASHINGTON, D.C. 20310-0103	1	COMMANDER ROCK ISLAND ARSENAL ATTN: SMCRI-ENM ROCK ISLAND, IL 61299-5000	1
ADMINISTRATOR DEFENSE TECHNICAL INFO CENTER ATTN: DTIC-FDAC CAMERON STATION ALEXANDRIA, VA 22304-6145	12	DIRECTOR US ARMY INDUSTRIAL BASE ENGR ACTV ATTN: AMXIB-P ROCK ISLAND, IL 61299-7260	1
COMMANDER US ARMY ARDEC ATTN: SMCAR-AEE	1	COMMANDER US ARMY TANK-AUTMV R&D COMMAND ATTN: AMSTA-DDL (TECH LIB) WARREN, MI 48397-5000	1
SMCAR-AES, BLDG. 321	1	COMMANDER	
SMCAR-AET-O, BLDG. 351N	1	US MILITARY ACADEMY	1
SMCAR-CC	1	ATTN: DEPARTMENT OF MECHANICS	
SMCAR-CCP-A	1	WEST POINT, NY 10996-1792	
SMCAR-FSA	1		
SMCAR-FSM-E	1	US ARMY MISSILE COMMAND	
SMCAR-FSS-D, BLDG. 94	1	REDSTONE SCIENTIFIC INFO CTR	2
SMCAR-IMI-I (STINFO) BLDG. 59	2	ATTN: DOCUMENTS SECT, BLDG. 4484	
PICATINNY ARSENAL, NJ 07806-5000		REDSTONE ARSENAL, AL 35898-5241	
DIRECTOR US ARMY BALLISTIC RESEARCH LABORATORY ATTN: SLCBR-DD-T, BLDG. 305	1	COMMANDER US ARMY FGN SCIENCE AND TECH CTR ATTN: DRXST-SD	1
ABERDEEN PROVING GROUND, MD 21005-5066		220 7TH STREET, N.E. CHARLOTTESVILLE, VA 22901	
DIRECTOR US ARMY MATERIEL SYSTEMS ANALYSIS ACTV ATTN: AMXSY-MP	1	COMMANDER US ARMY LABCOM	
ABERDEEN PROVING GROUND, MD 21005-5071		MATERIALS TECHNOLOGY LAB	
COMMANDER		ATTN: SLCMT-IML (TECH LIB)	2
HQ, AMCCOM		WATERTOWN, MA 02172-0001	
ATTN: AMSMC-IMP-L	1		
ROCK ISLAND, IL 61299-6000			

NOTE: PLEASE NOTIFY COMMANDER, ARMAMENT RESEARCH, DEVELOPMENT, AND ENGINEERING CENTER, US ARMY AMCCOM, ATTN: BENET LABORATORIES, SMCAR-CCB-TL, WATERVLIET, NY 12189-4050, OF ANY ADDRESS CHANGES.

TECHNICAL REPORT EXTERNAL DISTRIBUTION LIST (CONT'D)

	NO. OF COPIES		NO. OF COPIES
COMMANDER US ARMY LABCOM, ISA ATTN: SLCIS-IM-TL 2800 POWDER MILL ROAD ADELPHI, MD 20783-1145	1	COMMANDER AIR FORCE ARMAMENT LABORATORY ATTN: AFATL/MN EGLIN AFB, FL 32542-5434	1
COMMANDER US ARMY RESEARCH OFFICE ATTN: CHIEF, IPO P.O. BOX 12211 RESEARCH TRIANGLE PARK, NC 27709-2211	1	COMMANDER AIR FORCE ARMAMENT LABORATORY ATTN: AFATL/MNF EGLIN AFB, FL 32542-5434	1
DIRECTOR US NAVAL RESEARCH LAB ATTN: MATERIALS SCI & TECH DIVISION CODE 26-27 (DOC LIB) WASHINGTON, D.C. 20375	1 1	MIAC/CINDAS PURDUE UNIVERSITY 2595 YEAGER ROAD WEST LAFAYETTE, IN 47905	1
DIRECTOR US ARMY BALLISTIC RESEARCH LABORATORY ATTN: SLCBR-IB-M (DR. BRUCE BURNS) ABERDEEN PROVING GROUND, MD 21005-5066	1		

NOTE: PLEASE NOTIFY COMMANDER, ARMAMENT RESEARCH, DEVELOPMENT, AND ENGINEERING CENTER, US ARMY AMCCOM, ATTN: BENET LABORATORIES, SMCAR-CCB-TL, WATERVLIET, NY 12189-4050, OF ANY ADDRESS CHANGES.